


CSBO Update
November 2015



Bus Referrals. 43 behavior referrals written this school year compared to 84 last year August-October.



Annual ROE Health Life Safety Inspection. Completed October 14. All findings were minor and District responses are attached.

ROE HEALTH LIFE SAFETY BUILDING INSPECTION

Listed below is a response to each of the areas that were cited on the recent ROE Health Life Safety building inspections in the Geneseo CUSD #228 on October 14, 2015. The responses have also been uploaded as required to the IARSS HLS System.

Millikin Elementary School	
Extension cord providing power to a power stip.	Extension cord has been removed in music room.
Northside Elementary School	
Extension cord is being used in a permanent application.	Extension cords have been removed in offices, cafeteria, and teacher room.
24" of clearance from shelving to ceiling in non-sprinkler buildings.	Items on top shelves in janitor storage has been removed.
36" of clearance must be maintained around electrical panels.	Clearance in the boiler room electrical panel has been adjusted for 36".
Southwest Elementary	
Extension cord is being used in a permanent application.	Extension cord has been removed in the art room.
Geneseo Middle School	
18" of clearance must be maintained above storage in a sprinklered building.	Items on top shelf in room 817 storage have been removed.
Extension cord providing power to a power stip.	Extension cords have been removed in rooms 712, 817, and 710.
Alcohol hand rub dispensers are prohibited in carpeted areas.	Maintenance will supply hand dispensers with a non-alcohol hand rub product.
Geneseo High School	
Egress is obstructed in wrestling room and music hall.	Items have been relocated that were obstructing the egress.
Fire detector is required in storage closets.	A fire detector in the janitor closet off of the cafeteria will be installed by our maintenance staff.
24" of clearance from shelving to ceiling in non-sprinkler buildings.	Items on top shelves in home economics, music storage, and wrestling room storage have been taken down and stored properly.
Flammable liquids must be stored in approved cabinets.	Flammable liquids that were in the storage closet across from Life Skills room have been removed.
Extension cord is being used in a permanent application.	Extension cord in room 3 has been removed.
Electrical panels	A "blank" has been fitted into the electrical panel in south hallway to fill empty slot.
36" of clearance must be maintained around electrical panels.	Clearance in the music, stage, and room 47 storage around electrical panels has been adjusted for 36".