



October 21, 2013

Mr. William Kested
 Regional Office of Education, Bureau, Henry, and Stark Counties
 107 South State Street
 Atkinson, IL 61235

Dear Mr. Kested:

Listed below is a response to each of the areas that were cited on your recent building inspections in the Geneseo CUSD #228 on October 16, 2013.

Millikin Elementary School	
Music room office being used for storage, no fire detector.	District architect will be consulted per your recommendation.
Music room extension cord being used to power a permanent device.	Extension cord has been replaced with a power strip.
Southwest Elementary School	
Fire extinguisher tag in library has expired.	Tag will be updated by Tri-State Fire Control, Inc.
Northside Elementary School	
Alcohol hand-rub dispenser prohibited in carpeted areas.	This hand-rub dispenser has been removed from the carpeted area.
Geneseo High School	
Hold open devices (door stops) are prohibited on doors with closers.	Door stops in the back hall and band hall have been removed.
Emergency lighting failed testing.	Bulbs in emergency lights by room 22 and wrestling room hallway have been replaced.
24" of clearance from shelving to ceiling in non-sprinkler buildings.	Items on top shelves in band storage, stage storage, and J2 have been re-adjusted.

Please let me know if you need anything else. Thank you.

Sincerely,

Tim Gronski, Director of Support Services

cc: Mr. Scott Kuffel, Superintendent
 Geneseo CUSD #228 Board of Education