



October 7, 2014

Mr. William Kested
 Regional Office of Education, Bureau, Henry, and Stark Counties
 107 South State Street
 Atkinson, IL 61235

Dear Mr. Kested:

Listed below is a response to each of the areas that were cited on your recent building inspections in the Geneseo CUSD #228 on September 29, 2014.

Millikin Elementary School	
24" of clearance from shelving to ceiling in non-sprinkler buildings.	Items on top shelves in room 6 have been taken down and stored properly.
Fire Extinguisher tag has expired.	Tag will be updated by Tri-State Fire Control, Inc.
Extension cord providing power to a power strip.	Extension cord has been removed in room 15.
Ceiling decorations in combination with lights is likely a fire hazard.	Decorations have been removed and displayed in an alternative location.
Northside Elementary School	
Multi-plug extension cord is being used instead of a power strip.	Extension cord has been replaced with a longer power strip.
Geneseo Middle School	
Boiler Room inspection certificates have expired.	All district boilers were inspected on Sep 29 th , 2014 and the certificates are displayed properly.
Extension cord providing power to a power strip.	Extension cord has been removed in room 606.
Geneseo High School	
Boiler Room inspection certificates have expired.	All district boilers were inspected on Sep 29 th , 2014 and the certificates are displayed properly.
Fire detector is required in storage closets.	A fire detector in the janitor closet off of the cafeteria will be installed by our maintenance staff.
24" of clearance from shelving to ceiling in non-sprinkler buildings.	Items on top shelves in home economics, music storage, and wrestling room storage have been taken down and stored properly.

Please let me know if you need anything else. Thank you.

Sincerely,

Tim Gronski, CSBO